

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

1239
ENE
> 1
1.604 mi.
8468 ft.

2556 EAST 19TH ST
2556 EAST 19TH ST
BROOKLYN, NY

NY Spills S103274224
N/A

Relative:
Higher

Actual:
10 ft.

SPILLS:

Name: 2556 EAST 19TH ST
Address: 2556 EAST 19TH ST
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9801684 / 2011-05-06
Facility ID: 9801684
Facility Type: ER
DER Facility ID: 164848
Site ID: 198085
DEC Region: 2
Spill Cause: Unknown
Spill Class: C1
SWIS: 2401
Spill Date: 1997-10-01
Investigator: SFRAHMAN
Referred To: Not reported
Reported to Dept: 1998-05-07
CID: Not reported
Water Affected: Not reported
Spill Source: Private Dwelling
Spill Notifier: Affected Persons
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1998-05-08
Spill Record Last Update: 2011-05-06
Spiller Name: Not reported
Spiller Company: 2556 EAST 19TH ST
Spiller Address: 2556 EAST 19TH ST
Spiller Company: 001
Contact Name: Not reported
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was
MULQUEEN TEMP SPILL # 37 NEIGHBOR HAS RETURNED FROM BEING OUT OF THE
COUNTRY AND HAS CLEANED UP SPILL. CALLER WOULD LIKE CASE TO STAY
ACTIVE FOR ONE YEAR TO SEE IF IT HAPPENS AGAIN. 06/16/06: This spill
is transferred from Mike Mulqueen to Mr. Koon Tang. 10/13/10 - Austin
- Spill being transfered from Tang to Region 2 Spills staff - end
01/11/11 Letter sent out to Mohammad Jamil 2556 East 19th Street
Brooklyn, NY 11235-3520(sr) No response received from home owner. Case
is almost thirteen years old. No complain received about the oil

Remarks:

smell since then. Case administratively closed."
"(temp spill # 37) subj that live at above address move their oil
burner since that time there has been oil leaking (smell) coming from
th house. comp lives next door"

All Materials:

Site ID: 198085
Operable Unit ID: 1062222
Operable Unit: 01
Material ID: 323607
Material Code: 0001A

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported